



## MATERIALS SAFETY DATA SHEET

### MSDS # 1141 - ROOFCRAFT PRIMER ASPHALT ROOF AND FOUNDATION (SOLVENT BASE)

VI - REACTIVITY DATA	
CHEMICAL	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
CONDITIONS TO AVOID: Avoid heat and open flames	
INCOMPATIBILITY (SUBSTANCE TO AVOID) Strong oxidizing agents may ignite the product.	
CONDITIONS OF REACTIVITY Not applicable	
HAZARDOUS DECOMPOSITION PRODUCTS Will not decompose under normal conditions of handling or warehousing.	

VII - TOXICOLOGICAL PROPERTIES			
THRESHOLD LIMIT VALUE 100 ppm for solvent portion.		LC50/LD50 (ESTIMATED) LD50 (oral-rat)=5g/kg LC50 (inhalation-rat) = 5 g/m <sup>3</sup>	
ROUTE OF ENTRY	<input checked="" type="checkbox"/> SKIN CONTACT	<input type="checkbox"/> SKIN ABS	<input checked="" type="checkbox"/> EYES
EFFECTS OF ACUTE EXPOSURE	Inhalations of high concentrations of vapours can cause headache, dizziness, nausea and unconsciousness. Can cause gastro-intestinal irritation, nausea, vomiting, diarrhea. If ingested in large quantity		
EFFECTS OF CHRONIC EXPOSURE	Prolonged or repeated contact with skin will cause irritation, defatting, dermatitis. Vapours may also irritate eyes, nose and throat		
IRRITANCY	Skin irretancy after prolonged or repeated contacts.	SENSITIZATION Not available	SYNERGISTIC MATERIALS Not available
<input type="checkbox"/> CARCINOGENICITY	<input type="checkbox"/> REPRODUCTIVE EFFECTS	<input type="checkbox"/> TERATOGENICITY	<input type="checkbox"/> MUTAGENICITY
Product not believed to cause any of these effects.			

VIII - FIRST AID MEASURES	
SKIN	Thoroughly wash exposed areas with soap and water or waterless hand cleaner
EYES	Flush eyes thoroughly with plenty of lukewarm water. Get medical attention.
INHALATION	Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Call a physician
INGESTION	<b>DO NOT INDUCE VOMITING.</b> If vomiting, take care to prevent aspiration into lungs Keep person warm, quiet and get medical attention.

IX - PREVENTIVE MEASURES	
PERSONAL PROTECTIVE EQUIPMENT	<b>EYES:</b> Safety goggles if applied by spray. <b>GLOVES:</b> Suggested (neoprene, nitrile) <b>CLOTHING:</b> Oil resistant apron and <b>RESPIRATORY:</b> Approved organic vapour mask in confined areas if applied by spray
ENGINEERING CONTROLS (VENTILATION, ETC.)	Exhaust ventilation required in confined areas. Local exhaust, if necessary to maintain TLV
LEAK AND SPILL PROCEDURE	Avoid breathing fumes and contact with skin and eyes. Avoid all sources of ignition. Contain spill with sand or earth. Remove to disposal container.
WASTE DISPOSAL	Approved incineration or sanitary landfill as per
HANDLING PROCEDURE	Normal
STORAGE REQUIREMENTS	Store in cool, well-ventilated areas. Keep away from ignition sources.
SHIPPING INFORMATION	TDG regulations not applicable for shipments by road vehicle of 454L or less. Tars, liquid: UN1999: Class 3. Packing Group III.

While Bramcal Production Co. believes that the data contained herein are factual and opinions expressed are those of qualified experts regarding the results of the tests conducted, the data is not to be taken as warranty or representation for which Bramcal Production Co. assumes legal responsibility. These are offered solely for your consideration, investigation and verification. Any use of this data and information must be determined by the user to be in accordance with federal, provincial/state or municipal laws and regulations.

BRAMCAL

Page 2 of 2

